

PROJECT BRIEF – Historic District Board of Review Application for Certificate of Appropriateness at 1030 Park Ave. to build a garage on the vacant lot adjacent to the house and to replace and enclose rear second and third floor decks together.



Current Zoning: Historic District Residential (HDR)	Project Location: 1030 Park Ave.
Applicant: Robin Mingione	Owner: same

Preliminary Staff Recommendation: Approve

Conditions:

1. N/A

Reasoning:

Project is in conformance with the guidelines.

History, Relevant Information, & Prior Approvals: History:

Likely built by Benjamin and Martha Brushfield, who immigrated to

Madison from England in 1832. It does not appear in the 1854 Madison map and may have been built soon after. (All new interior, nine fireplaces, recreated poplar woodwork interior. Post and beam construction, 2002)

Relevant Information:

N/A

Prior Approvals:

N/A

Alterations, Historical Information, & Prior Approvals:

Date	c. 1855	
Style	Federal	
Evaluation	Contributing	
Survey Notes		

Guidelines, Standards, & Ordinances

HDBR Guidelines: Madison Historic District Design Guidelines – 24.0 New Construction - Additions p. 106-108


Ordinance: 151.34 Visual Compatibility Factors

HISTORIC RESOURCE INVENTORY FORM

Resource Address: 1030 Park Ave Madison Indiana 47250 USA		746	A ROLL OF THE STATE OF THE STAT
County: Jefferson	erpela della conferia finale, anche con provincia di comme con anticomi contro contro contro con provincia di contro con accominanti con provincia di contro con accominanti c		
Historic name: Brushfield House		1/1	
Present name:			
Local place name:			
Visible from public right of way: Yes	$(Add (e^{-i\phi} - e^{-i\phi} + e^{-i\phi} - e^{-i\phi}))) = m_0 (e^{-i\phi} - e^{-i\phi} - e^{-i\phi} + e^{-i\phi} - $	// // m	
Ownership: Private	1 + a + a + b + b + a + b + a + b + a + b + a + b + a + b + a + b + a + b + a + b + a + b + a + a		
Owner/Address:			100-4-1
Land unit size:	$\langle \phi_{1}^{2} \phi_{1}^{2} \phi_{2}^{2} \phi_{3}^{2} \phi_{4}^{2} \phi_{3}^{2} \phi_{4}^{2} \phi_{3}^{2} \phi_$		
Site/Setting: Ground drops sharply to south,	creating split level. Broken payement		31 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
in front. Mature trees.	ereating spin reven broken pavement		
	The second secon	Lat/Long: 38.73367253006388	50, -85.3643711221248800 [WGS84]
		UTM: Zone 16S, 642165.6282	
		Parcel No. GIS/Ref/ID: 32064	t takan dibinaman banan kan dan kan kan kan kan pangan pangan kan kan pangan kan banan banan banan banan kan ka
Historical Information		 по в прети по прети по прети прети по прети	$q_{ij}(x_i,x_i,x_j) = (x_i,x_i,x_j) + (x_i,x_i,x_i,x_i,x_i,x_j) + (x_i,x_i,x_i,x_i,x_j) + (x_i,x_i,x_i,x_i,x_i,x_i,x_i,x_i,x_i,x_i,$
Historic Function: Domestic: Single Dwellin	g	Current Function: Vacant/Not i	in Use
Construction Date: ca. 1850-1859, circa 185	5*	Architect:	a_{1}
Original or Significant Owners: Benjamin &	Martha Brushfield	Builder:	raka periorije objektivit post žemovnom krakama indenkulturu tojek programa produce a falininki (indostrbit uda unbat aphrong monatriaka
Significant Date/Period:		Developer:	the and a sea of a se
Areas of Significance: Architecture Commu	nity Planning and Development	он общення в решировання (в 1940 гр.), на може образова Мондово (в 1941 гр.), на принценення в 1941 гр.), на продуст в 34 гр.), на прости в 34 гр.), на продуст в 34 гр.), на продуст в 34 гр.), на прости в 34 гр.), на продуст	
Architectural Information		alande (f. p.) and an er per pelasis as in the colorisation passing a sign and a gade of a deal of a colorisation passing an engineering a special sign.	والمنافظة والمنا
Category: building, House	Style: Federal	на (Дона) (Дона) (Дона) (ТОН) и водо Намения (Винония водо поможения быльный ред в Месрейрер), Дона на дона (Болошена, переда	Additions
Structural: masonry	Exterior Material(s): br	ne tick	✓ Additions ✓ Alterations
Stories: 2, Bays:		Roof Material: replacement asphalt shingles Move	
Form or Plan: I-House, rectangular		, flush eaves , corbelling	Other
Foundation: rubblestone	A TO SECURE AND A SECURI AND A SECURE AND A SECURE AND A SECURE AND A SECURE AND A SECURITARIZED AND A SECURE	vinyl 6/6 double-hung sashes	Ancillary structures: 1 total including domestic
General condition: Poor	Chimney(s): two brick		building
Basement:	Porch:		
Historical Summary: .ikely built by Benjamin and Martha Brushfie lave been built soon after. (All new interior, n	eld, who immigrated to Madison from ine fireplaces, recreated poplar woodw	England in 1832. It does not appoor work interior. Post and beam cons	ear in the 1854 Madison map and may truction. 2002)
Status (Current Listing or Designation) National: indiv. district landmrk. State/Province: indiv. district landmrk. Local: indiv. district landmrk.	Evaluation (Preparer's Assessment Recommendation ☐ Individually eligible ☑ Eligible as contributing resource ☐ Not eligible / non-contributing ☐ Not determined	of Eligibility) Level of potential eligibility National State Local	Landmark potential National State Local
982, Madison Local Historic District	Eligibility: Applicable NHL Criteria: 1, 4		

1030 Park Ave Madison, Indiana (pg. 2)





Description/Remarks

This is a 2-story house in the Federal style built in 1855. The structural system is masonry. The foundation is rubblestone. Exterior walls are brick. Brick is common bond. The building has a side gable roof clad in replacement asphalt shingles with flush eaves and corbelling. Side gabled low pitch, brick corbelling and dentils at front facade. There are two sides, brick chimneys. Chimneys covered in tarp. Windows are replacement vinyl, 6/6 double-hung sashes. 6/6 replacement windows with flat dressed slightly pedimented stone lintels and sills. Historic wood paneled door with partially missing surround (bracketed cornice with dentils 2002).

Survey and Recorder

Project: Madison, Indiana	Sequence/Key no.:	Survey Date: December 2021
Prepared By: Douglas Gilbert, The Lakota Group/Douglas Gilbert Architect	Report Title/Name: Madison Local Historic District Update	Previous Surveys: Madison Reconnaissance Survey (2002-2004) ID #32064, surveyed Sep 25, 2002, Site Number 4-134
Inventoried: 09/20/2021 11:43:57 am Last updated: 06/24/2022 11:57:04 am by Doug Kaarre / 312.467.5445 x 220	Level of Survey: ☑ Reconnaissance ☐ Intensive	Additional Research Recommended? Yes No

HDCA-25-23

Certificate of Appropriateness (COA) Application

Status: Active Submitted On: 3/4/2025

Primary Location

1030 PARK AVE MADISON, IN 47250

0wner

Prickett Mark STATE ST 424 MADISON, IN 47250

Applicant

Robin Mingione 812-493-3707

@ robin.mingione@exprealty.com

47 Country Manor Madison, IN 47250

Internal Review

	Staff	Completing	Online	Form
--	-------	------------	--------	------

 \square

Send for HDBR review

2

Approval/Denial Date

__

Name and Title of Reviewer

Additional Comments

Motification Sign

2

â incomplete signs paid by credit card?

Approved/Denied

_

General Information

Are you the owner?*

Yes

Legal Description of Property

1030 Park Ave., Madison, IN 47250


Will you be working with a Contractor?


Zoning Classification


HDR

Description of Existing Use	
single family residence (dilapidated/vacant)	
Description of Proposed Use	
single family residence	
Type of Project	
Select which applies to your project.*	Define Other 🚱
Restoration, Rehabilitation, or Remodel	
Select which applies to your project.* New Building	Define Other <i>€</i>
Description(s) of Work	
Scope of Work*	
building a garage on the vacant lot adjacent to the house, replace (board) restoration of front stoop, replacement of windows, replacement	
Building Elements	
Architectural Details	Existing Material*
	NA
Proposed Material*	Awnings & Canopies
wood/steel	
Chimneys	Deck
Demolition	Doors & Entrances
	eq


Existing Material*	Proposed Material*
metal	wood
Fences and Walls	Fire Escapes & Staircases
Foundations	Gutters & Downspouts
Historic Garages & Outbuildings	Lighting
New Construction/Addition	Pools, Fountains, Gazebos and Pergolas
Porch Columns & Railings	Porches
Ramps and Lifts	Roofs
Shutters	Siding
Signage	Storefronts
Storm Doors and Storm Windows	Utilities
Windows	Other








Front Portico Conceptual Addition




Current Front Elevation



Current Rear Elevation




Future Conceptual Design- lower level open patio Story 1 & 2 closed in glass rear with metal roof, steel/wood structure




Another conceptual Rear elevation – lower level will not be enclosed




Similar design in downtown Madison on Main Street



Front Wall/fence conceptual



prefer hard siding walls and metal roof. — May add brick/stone accent To be built after house is complete. Carriage House Conceptual in Downtown- New construction Similar size street view to new construction garage



Application for Certificate of Appropriateness

SITE PLAN
Stephen & Robin Mingione
1030 Park Ave.

Legend:

В

A 8 ft. x 6' 6" ENTRY PORTICO

23' x 27' ADDITION

C 20 ft x 50 ft CARRIAGE HOUSE

Existing two-story brick building




DETAIL - Entry Portico Stephen & Robin Mingione1030 Park Ave.

View from Northwest



DETAIL - Entry Portico Stephen & Robin Mingione1030 Park Ave.

View from Southeast



PLAN - First Floor Stephen & Robin Mingione 1030 Park Ave.

Legend:

A 'In-kind' replacement of existing vinyl windows with new vinyl windows

New Front Portico

B Existing Brick

D Gutter




FRONT Elevation - New Portico/Entry Stephen & Robin Mingione 1030 Park Ave.

Legend:

- A 'In-kind' replacement of existing vinyl windows with new vinyl windows
- New Front Portico

B Existing Brick

D Existing Front Door, Protect during construction, Paint and Repair



East Elevation Stephen & Robin Mingione 1030 Park Ave.

Legend:


REAR ADDITION:

'Hardiboard' clapboard siding

New Front Portico


B Existing Brick

D Gutter



Application for Certificate of Appropriateness

Rear Elevation - Deck Enclosure Stephen & Robin Mingione 1030 Park Ave.



West Elevation Stephen & Robin Mingione 1030 Park Ave.


Legend:

A 'In-kind' replacement of existing vinyl windows with new vinyl windows

C New Front Portico

B Existing Brick

D Gutter



Entry Portico - FRONT ELEVATION scale: 3/8" = 1'-0"

Entry Portico - LEFT SIDE ELEVATION scale: 3/8" = 1'-0"

Application for Certificate of Appropriateness

DETAIL - Entry Portico Stephen & Robin Mingione1030 Park Ave.