PROJECT BRIEF

Historic District Board of Review Application for Certificate of Appropriateness at 810 E. Second St. to replace existing aluminum siding with Dutch-lap vinyl siding.

Application Date: March 6, 2023 HDBR Meeting Date: March 27, 2023



Project Description:

Certificate of Appropriateness application to replace existing aluminum siding with Dutch-lap vinyl siding.

Current Zoning:

Project Location:

Historic District Residential (HDR)

810 E. Second St.

Applicant:

Joel Storm 2224 Seneca Dr. Madison, IN 47250 Owner:

Mark Timmons 810 E. Second St. Madison, IN 47250

Supporting Documents:

COA application
Photos of property
Sample of vinyl siding
Owner consent form
Copy of HDBR meeting public sign
GIS map

Alterations, Historical Information, & Prior Approvals:

Date	c. 1860	
Style	Vernacular Gable-front	
Evaluation	Contributing	
Survey Notes		

Alterations:

Aluminum siding installed on top of historic wood siding; wood awning added over front door

Historical Information/Misc. Important Information:

COA for Cementous siding to replace existing aluminum siding issued 12/2022 – no application to amend siding material; project to install vinyl siding started without an approved COA or application;

staff noted a decorative attic vent on the front gable peak that had been previously covered by the aluminum siding.

Prior COA Approvals:

1/2021 – wood awning over front entrance, storm windows, metal & full glass storm door

Guidelines, Standards, & Ordinances

HDBR Guidelines:

Madison Historic District Design Guidelines - 3.0 Materials, Wood Siding & Shingles p. 44-48

- 3.1 Retain and preserve historic wood siding, shingles, trim, ornamentation, and other wood decorative elements.
- 3.2 Maintain existing original wood siding, shingles, trim, ornamentation, and other wood decorative elements.
- 3.3 Repair existing wood elements wherever possible. Use preservation techniques which encourage repair (such as epoxies, splicing, and patching where applicable) rather than wholesale replacement.
- 3.4 Replace historic wood elements only where the original is too deteriorated to repair. If replacement is necessary, use new replacement wood that matches the original as closely as possible in all properties: shape, profile, texture, exposure, and detailing. The deteriorated or damaged condition should be documented. Replacement in kind does not normally require a COA.
- 3.5 If a portion of a historic wall is deteriorated beyond repair, replace only the damaged portion.
- 3.8 The use of vinyl or aluminum siding or trim is not appropriate. The HDBR may allow the replacement of existing synthetic siding with new substitute siding if the proposed replacement will be in keeping with the original appearance of the structure. If the removal of synthetic siding reveals historic siding intact beneath, the historic siding shall be preserved and retained.
- 3.9 The use of fiber cement (cementitious) siding may be approved for replacement of deteriorated wood siding, new structures, non-historic structures and additions to historic structures not visible from the public view.
- 3.10 Avoid removing or replacing such features as cornices, brackets, pilasters, door and window moldings, pediments, medallions, dentil and modillion molding, corner boards, and other character-defining architectural trim, particularly from the principal façade.

Conformance with Guidelines, Ordinance & Standards:

The project is *not in* conformance with Siding Guidelines 3.1-3.5 because the historic wood siding appeared intact and in good condition underneath the aluminum siding; is *not in* conformance with Siding Guidelines 3.8 because the vinyl siding is not appropriate, especially when concealing the original historic wood siding; is *not in* conformance with Guideline 3.9 because there is not enough evidence the historic wood siding is deteriorated to the point to warrant replacement even with an appropriate replacement siding material; is *not in* conformance with Guideline 3.10 because the aluminum siding was covering the attic vent on the front gable peak and the proposed siding may also cover it; is *not in* conformance with the ordinance §151.34 because is *not* in conformance with SIS for Preservation because the project will replace intact historic materials.

Ordinance:

§151.34 Visual Compatibility Factors

(G) Relationship of materials, and texture. The relationship of materials, and texture of the facade of a building shall be visually compatible with the predominant materials used in the buildings to which it is visually related.

Secretary of the Interior Standards:

Standards for Preservation

2. The historic character of a property will be retained and preserved. The replacement of intact or repairable historic materials or alteration of features, spaces and spatial relationships that characterize a property will be avoided.

Preservation Brief:

#8 – Aluminum and Vinyl Siding on Historic Buildings: The Appropriateness of Substitute of Materials for Resurfacing Historic Wood Frame Buildings





HDCA-23-23

Certificate of Appropriateness (COA) Application

Status: Active

Date Created: Mar 6, 2023

Applicant

Joel Storm joel@stormcontractingllc.com 2224 Seneca Dr. Madison, IN 47250 812-821-5493 **Primary Location**

810 E SECOND ST MADISON, IN 47250

Owner:

Timmons Mark & Bobbie Jo 810 EAST SECOND STREET MADISON, IN 47250

Internal Review

Notification Sign

2

Send for HDBR review

 \mathbf{S}

Approval/Denial Date

03/27/2023

General Information

Are you the owner?

No

Zoning Classification

HDR

Will you be working with a Contractor?

Yes

Description of Existing Use

residential

Description of Proposed Use

residential

Property Owner Information

Contractor Information

Company Name

Storm Contracting dba Roof-aid

License Number

1354

Email

joel@stormcontractingllc.com

City

Madison

Zip Code

47250

Contractor Name

Joel Storm

Phone

812-821-5493

Mailing Address

2224 Seneca Dr

State

IN

Type of Project

Select which applies to your project.

Restoration, Rehabilitation, or Remodel

Description(s) of Work

Scope of Work

replace the existing cementous siding with Dutch-lap vinyl siding

Acknowledgement

Please read the following statements. Your signature below acknowledges that you have read the statements and attest to their accuracy:

- I understand that the approval of this application by City Staff or the HDBR does not constitute approval of other federal, state, or local permit applications
- I understand that I (or my representative) will need to attend the HDBR Hearing. If no representation is present at the meeting, the

Digital Signature

Joel Storm 03/06/2023 application will be deemed incomplete and will be placed on the next month's agenda

- I have reviewed the City of Madison's "Historic Distrcit Guidelines" in preparing this Application.
- I understand that I must post the notification sign(s) provided by the HDBR on site for 15 consecutive days immediately prior to the meeting on which my application will be heard by the HDBR.

Attachments

Owner Consent.pdf Uploaded by Brooke Peach on Mar 6, 2023 at 2:07 pm



810 E. Second St. 1.jpg Uploaded by Brooke Peach on Mar 6, 2023 at 10:31 am

History

Date	Activity
Mar 6, 2023 at 10:08 am	Brooke Peach started a draft of Record HDCA-23-23
Mar 6, 2023 at 11:03 am	Brooke Peach submitted Record HDCA-23-23
Mar 6, 2023 at 11:03 am	approval step Application Reviewwas assigned to Brooke Peach on Record HDCA-23-23
Mar 6, 2023 at 11:47 am	Brooke Peach assigned approval step Historic Preservationist Review to Brooke Peach on Record HDCA-23-23
Mar 6, 2023 at 12:56 pm	Brooke Peach assigned approval step Director of Planning Review to Nicole Schell on Record HDCA-23-23

HISTORIC RESOURCE INVENTORY FORM

	OIL I OIL			
Resource Address: 810 E 2nd St Madison Indiana 47250 USA		WA		
County: Jefferson				No.
Historic name:			國果盟	
Present name:				
Local place name:		THE HALL		11
Visible from public right of way: Yes			B 14 88	
Ownership: Private				The second
Owner/Address:				
Land unit size:		100	W 75	The second
Site/Setting: On slight rise. Linear walk to fro side.	ont. Mature trees. Alley is at the west		mar year	Marie Manager
		T . /T		
		Lat/Long: 38.7349960686573500		
		UTM: Zone 16S, 641658.9502 m Parcel No.	E, 4288630.3756	mN
		Parcer No.		
Historical Information				
Historic Function: Domestic: Single Dwelling		Current Function: Domestic: Single Dwelling		
Construction Date: ca. 1860-1869, circa 1860)*	Architect:		
Original or Significant Owners:		Builder:		
Significant Date/Period:		Developer:		
Areas of Significance: Architecture Commun	nity Planning and Development			
Architectural Information				
Category: building, House	Style:			Additions
Structural: frame	Exterior Material(s): al	uminum siding		✓ Alterations
Stories: 2, Bays:	Roof Material: replace	ment asphalt shingles		Moved
Form or Plan: Vernacular, rectangular	Roof Type: Gable Fron	t , box cornice , decorative bargebo	oard	Other Ancillary structures:
Foundation: not visible	Windows: historic woo	d 4/4 double-hung sashes		
General condition: Good	Chimney(s):			
Basement:	Porch: single-story wra	p-around deck		
Historical Summary:				
Status (Current Listing or Designation) National: indiv. district landmrk. State/Province: indiv. district landmrk. Local: indiv. district landmrk. 2006, Madison National Historic Landmark District	Evaluation (Preparer's Assessmen Recommendation Individually eligible Eligible as contributing resource Not eligible / non-contributing Not determined	t of Eligibility) Level of potential eligibility National State Local	Landmark pote National State Local	ntial

Eligibility: Applicable NHL Criteria: 1, 4

1982, Madison Local Historic District

Inventory Sheet: 810 E 2nd St Madison Jefferson Indiana






Description/Remarks

This is a 2-story house built in 1860. The structural system is frame. The foundation is not visible. Exterior walls are aluminum siding. The building has a gable front roof clad in replacement asphalt shingles with box cornice and **decorative** bargeboard. Medium pitch with boxed cornice, single pendant (modern) at gable end. Windows are historic wood, 4/4 double-hung sashes. There is a single-story, wrap-around deck. Replacement door with transom and canopy.

Survey and Recorder

Project: Search for '810 e 2' in Madison, Indiana (13 results)	Sequence/Key no.:	Survey Date: December 2021
Prepared By: Douglas Gilbert, The Lakota Group/Douglas Gilbert Architect	Report Title/Name: Madison Local Historic District Update	Previous Surveys: Madison Reconnaissance Survey (2002-2004), surveyed Oct 01, 2002, Site Number 4-196
Inventoried: 09/20/2021 11:44:00 am Last updated: 06/01/2022 7:20:52 pm by /	Level of Survey: Reconnaissance Intensive	Additional Research Recommended? Yes No







PROPERTY OWNER AUTHORIZATION FORM

I/We, MARK A.	Immon 5	hereby authorize
(Property Owner(s) – Please Print)		
Joel Storm	, representative for Storm	Contracting
(Applicant's Name)	(Compar	y, Firm, Organization)
to make application for a Certificate o	f Appropriateness	to
	(Type of Permit)	
replace the siding		at
(Desci	ription of Proposed Work)	
810 E. Second St. (Property Address)		
Madison, IN 47250		
(City, State, Zip Code)		
MAUR Jew (Property Owner Signature)	mora)	03/06/23

MADISON HISTORIC DISTRICT BOARD OF REVIEW Request for Certificate of Appropriateness



) Joel Storm
n has been made by: (name) ~
; by: (
made
peen
has
atio
Applica
⋖

Property Address: (address) 810 E. Second St.

Proposed Action to: (explain) replace existing cementous siding with Dutch-lap vinyl siding

Meeting will be held on: (date) 3/27/2023

POSTING DEADLINE

3/12/2023

City Hall — 101 W. Main Street, Madison, IN 47250

Place of Meeting:

5:30 PM Time of Meeting: All interested persons are welcome to attend this hearing to voice their objections or support for the application.

For further information, Contact the Office of Historic Preservation (812) 274-0253 or Plan Commission (812) 265-8324