### **PROJECT BRIEF**

Historic District Board of Review Application for Certificate of Appropriateness at 119 East St. to replace existing wood windows with aluminum clad wood windows of same size, shape, & design.

Application Date: April 3, 2023 HDBR Meeting Date: April 24, 2023



### Project Description:

Certificate of Appropriateness application to replace existing wood windows with aluminum clad wood windows of same size, shape, & design.

Current Zoning:

Project Location:

Historic District Residential (HDR)

119 East St.

Applicant:

Owner:

Ken & Linda Pettit

119 East St.

Madison, IN 47250

Same

### Supporting Documents:

COA application

Photos of property

Photos of windows

HABS photo

Letter from contractor & estimate

Copy of HDBR meeting public sign

GIS map

### Alterations, Historical Information, & Prior Approvals:

Date	c. 1870	
Style	Italianate	
Evaluation	Contributing	
Survey Notes		

### Alterations:

N/A

### Historical Information/Misc. Important Information:

This home was included in the Historic American Buildings Survey (HABS) conducted in the 1970s in Madison. Not all structures were included in HABS – only the most significant, well-preserved, and notable examples of various architectural styles. This structure was included in the Madison HABS. The windows are original historic wood windows and have the original hand-blown glass in most panes.

Staff did a site visit and examined the windows. The windows, while reportedly painted shut, were determined to be in excellent condition (some windows may be in need of scraping, painting, and areas of glazing but this was not widespread). There are also storm windows in place.

### Prior COA Approvals:

N/A

### Guidelines, Standards, & Ordinances

### HDBR Guidelines:

Madison Historic District Design Guidelines – 18.0 Windows p. 82-86

- 18.1 Retain and preserve historic windows including all significant related elements such as frames, sashes, shutters, hardware, old glass, sills, trim and moldings.
- 18.2 Maintain existing historic windows where possible. Follow guidelines for wood or metal maintenance, as relevant.
- 18.3 Repair existing historic windows where possible, rather than replacing entire window units. Use techniques such as wood epoxies and wood patches to repair and strengthen deteriorated wood elements. Replace only those elements that cannot be repaired. Reproduction glass is desirable but not required.

### Conformance with Guidelines, Ordinance & Standards:

The project is *not in* conformance with the Guidelines because the original historic windows are not deteriorated, can be easily repaired and made functional; is *not in* conformance with the ordinance §151.31 because the proposed replacement windows will not preserve the intact and solid historic windows and will alter the architectural character of the building; is *not in* conformance with SIS for Preservation because the proposed window replacement would remove intact and repairable historic materials and alter one of the most prominent features that characterize the architectural style and overall architectural character of the structure.

### Ordinance:

### §151.31 Preservation of Historic Buildings

A building or structure, classified as historic, and any appurtenance related thereto, including but not limited to stone walls, fences, iron work, steps, and signs, shall only be moved, reconstructed, altered, or maintained in a manner that will preserve the historical and architectural character of the building, structure, or appurtenance thereto.

### Secretary of the Interior Standards:


Preservation

2. The historic character of a property will be retained and preserved. The replacement of intact or repairable historic materials or alteration of features, spaces and spatial relationships that characterize a property will be avoided.

### Preservation Brief:

#9 The Repair of Historic Wooden Windows





### HDCA-23-40

Certificate of Appropriateness (COA) Application

Status: Active

**Applicant** 

Ken & Linda Pettit kpettit@cinergymetro.net 119 East St Madison, IN 47250 18125258464

Internal Review

**Notification Sign** 

1

**General Information** 

Are you the owner?

Yes

**Legal Description of Property** 

119 East Street, Madison In

Will you be working with a Contractor?

Yes

**Description of Existing Use** 

Residence

**Description of Proposed Use** 

Residence

**Contractor Information** 

**Company Name** 

Glass Unlimited

Date Created: Apr 3, 2023

**Primary Location** 

119 East Street Madison. IN 47250

Owner:

Ken & Linda Pettit 119 East St East Madison, IN 47250

Send for HDBR review

V

**Zoning Classification** 

**HDR** 

**Contractor Name** 

Melissa Prickett

License Number

27

**Email** 

NA

City

Madison

Zip Code

47250

Phone

812-273-3622/812-292-4000

**Mailing Address** 

807 Lanier

State

IN

### Type of Project

Select which applies to your project.

Restoration, Rehabilitation, or Remodel

### Description(s) of Work

Scope of Work

Remove 13 windows and replace with 13 SunClad Extruded Aluminum wood windows

### **Building Elements**

Windows

 $\mathbf{V}$ 

**Existing Material** 

wood

### **Proposed Material**

SunClad Extruded Aluminum Wood

### Acknowledgement

Please read the following statements. Your signature below acknowledges that you have read the statements and attest to their accuracy:

- I understand that the approval of this application by City Staff or the HDBR does not constitute approval of other federal, state, or local permit applications
- I understand that I (or my representative) will need to attend the HDBR Hearing. If no representation is present at the meeting, the application will be deemed incomplete and will be placed on the next month's agenda

**Digital Signature** 

Kenneth W. Pettit 04/03/2023

- I have reviewed the City of Madison's "Historic Distrcit Guidelines" in preparing this Application.
- I understand that I must post the notification sign(s) provided by the HDBR on site for 15 consecutive days immediately prior to the meeting on which my application will be heard by the HDBR.

### **Attachments**

Uploaded by ... on
Uploaded by ... on

Uploaded by ... on

Uploaded by ... on

Uploaded by ... on

Uploaded by ... on

### Timeline

Label		Status	Activated	Completed	Assignee	Due Date
	Application Review	Active	Apr 3, 2023 at 11:19 am	-	Brooke Peach	-
Samuel Sa	Fee Payment	Inactive	-	~	-	-
	Historic Preservationist Review	Inactive	-	-	-	•
	Director of Planning Review	Inactive	-	T.	-	w.
	HDBR Review	Inactive	-	~	-	~

## Glass Unlimited, Inc. Melissa Prickett

807 Lanier Drive, Madison, IN 47250 812-273-3622 glassunlimitedinc@cinergymetro.net



March 31, 2023

Ken Pettit 119 East Street Madison, IN 47250

Dear Ken Pettit,

It is our professional opinion that the existing windows (13) located at the above address are not feasible to repair. Our determination is the majority of the windows are either painted shut, non-operable, missing Passover pulley's, sash cords and weights, etc. Because of these issues the windows do not meet egress requirements and are a safety and health violation for the occupants.

We have provided you an estimate to replace the (13) windows with SunClad Extruded Aluminum wood windows. These windows are approved by the City of Madison Historical Board for the Historic District in Madison, IN.

Sincerely,

Melissa Prickett

Glass Unlimited, Inc. 807 Lanier Drive Madison, IN 47250 (812) 273-3622 phone

Name / Address

# **QUOTE**

Date	Estimate #
3/17/2023	Pettit3/17

Ken Pettit				
119 East St.				
Madison, IN 47250				
	Descri	ption		
Materials to Supply and Install:				
(*13) Sun USA Clad Architectural Dou Exterior/Bright White Interior, (*2) Wind Tempered Safety Glass in Bottom Sashes Extruded Screens, 1" SDL Colonial Grids	lows to be Ivory	Exterior/Ivory Interior.	(*2) Windov	vs to have
Exterior of Windows to be wrapped wir Existing shutters to be removed to allow	th color-matche winstallation of	d aluminum trim coil. the new windows.		
The price includes labor, all necessary sea and any debris.	alants, caulking,	fasteners, and the prope	r disposal of	the old windows
All materials is guarenteed to be as specified. All work in the above specifications involving ext	s to be completed in	9 workmonlike mana 1		
or deviation from the above specifications involving ext.  and above the estimate. All agreements contingent upon	ra costs will be execu strikes, accidents or	a workmanner manner according ited only upon written orders, and delays beyond our control.	ig to standard pra id will become ar	ctices. Any alteration nextra charge over
Authorized signature: Mlu Ja				
PAYMENT TERMS: Fifty (50) percent deposit - E	Balance upon comp	letion	Total	\$28,267.58
ACCEPTANCE OF ESTIMATE - The prices, specutherized to execute the work as specified. Payment	cifications and cond nt will be made as	ditions are satisfactory and ar outlined above.	e hereby approv	ed. You are
ignature				
				To the second se














### HISTORIC RESOURCE INVENTORY FORM

Resource Address: 119 East St Madison Indiana 47250 USA			
County: Jefferson			
Historic name: Genter House		VAF	
Present name:			AND DESCRIPTIONS
Local place name:			
Visible from public right of way: Yes			
Ownership: Private			
Owner/Address:			
Land unit size:		CONTRACTOR OF THE PARTY OF THE	AND ADDRESS OF THE REAL PROPERTY.
Site/Setting: Ground slopes south toward rive front and rear. Stribling iron fence, and ornate	r. There is a linear concrete path to gardens.	CONTRACTOR SAME AND ADDRESS OF	A THE PART WELL
		Lat/Long: 38.7333908000000	100, -85.3744993067458900 [WGS84]
		UTM: Zone 16S, 641285.809	6 mE, 4288445.5388 mN
		Parcel No. GIS/Ref/ID: 3208	36
Historical Information			
Historic Function: Domestic: Single Dwelling		Current Function: Domestic:	Single Dwelling
Construction Date: ca. 1870-1879, circa 1870	*	Architect:	
Original or Significant Owners:		Builder:	
Significant Date/Period:		Developer:	
Areas of Significance: Architecture Commun	nity Planning and Development		
Architectural Information			
Category: building, House	Style: Italianate		Additions
Structural:	Exterior Material(s): b		Alterations
Stories: 2, Bays:	Roof Material: asphal		☐ Moved ☐ Other
Form or Plan: 2/3 Double Pile, rectangular		le , Decorative cornice , brackets	Ancillary structures:
Foundation: stone		ood 4/4 double-hung sashes	1 total including carriage house
General condition: Excellent	Chimney(s):		
Basement:	Porch:		
Historical Summary:			
Status (Current Listing or Designation) National: indiv. i	Evaluation (Preparer's Assessment Recommendation ☐ Individually eligible ☑ Eligible as contributing resource ☐ Not eligible / non-contributing	nt of Eligibility)  Level of potential eligibility  National  State  Local	Landmark potential  National  State  Local

1982, Madison Local Historic District

Not determined

Eligibility: Applicable NHL Criteria: 1, 4

2006, Madison National Historic Landmark District


### 119 East St Madison, Indiana (pg. 2)

### Description/Remarks

This is a 2-story house in the Italianate style built in 1870. The foundation is stone. Exterior walls are brick (common bond). The building has a cross gable roof clad in asphalt shingles with decorative cornice and brackets. Side gable on front section, with a decorative Italianate bracketed cornice with pressed metal details. The rear extension has a rear-facing gable. Windows are original wood, 4/4 double-hung sashes. The first floor windows are full height. Windows have slightly pedimented stone lintels and sills, and shutters. Original wood panel door with ovate upper transom window. The projecting crown over the door has brackets and dentils.

Survey	and	Recorder
--------	-----	----------

Project: Search for '119 east' in Madison, Indiana (2 results)	Sequence/Key no.:	Survey Date: December 2021
Prepared By: Peggy Veregin, The Lakota Group/Douglas Gilbert Architect	\$	Previous Surveys: Madison Reconnaissance Survey (2002-2004) ID #32086, surveyed Oct 04, 2002, Site Number 4-283
Inventoried: 09/20/2021 11:44:03 am Last updated: 07/19/2022 5:37:01 pm by /	Level of Survey:  Reconnaissance Intensive	Additional Research Recommended?  Yes No



# **MADISON HISTORIC DISTRICT BOARD OF REVIEW** Request for Certificate of Appropriateness



Ken & Linda Pettit	
Application has been made bv: (name) Ker	•
e bv:	
mad	
been	
has ו	
plication	
Ap	•

Property Address: (address) 119 East St.

Proposed Action to: (explain) replace existing wood windows with aluminum clad wood windows of same shape, size, & design

Meeting will be held on: (date) 4/24/2023

City Hall — 101 W. Main Street, Madison, IN 47250 Place of Meeting:

Fime of Meeting: 5:30 PM

All interested persons are welcome to attend this hearing to voice their objections or support for the application.

or further information, Contact the Office of Historic Preservation (812) 274-0253 or Plan Commission (812) 265-8324

**POSTING DEADLINE** 

4/09/2023